M/T - 6 Speed MTM Difficulty Selecting Gears
TRANSMISSION & CLUTCH
TC002-01

September 14, 2001

Title:
6-SPEED MTM

Models:
'00 - '01 Celica GTS

Introduction

In order to assist drivers that have experienced difficulty selecting gears, production changes have been made to the shift cables, shift select mechanism, and internal transaxle components.

Applicable Vehicles
^ 2000 - 2001 model year Celica GTS with 6 - Speed MTM.

MODEL	STARTING VIN
2001 Celica GTS, 6 Speed	JTDDY32T#10049042

ZOOM SIZED FOR PRINT

Production Change Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	REPAIR MANUAL ILLUSTRATION SECTION MX(C60)
33205–20020	33205–20021	Shaft Sub–Assy, Gear Shift Fork No. 1	MX10
33232–12012	33232–20020	Head, Gear Shift, No. 1	
33244–20050	33244–20051	Shaft, Gear Shift Fork, No. 3	
33251–20060	33251–20080	Lever, Shift Inner No. 1	MX47
33266–20030	33266–20040	Shift Interlock Plate	
90501–18122	90501–18127	Spring, Compression, No. 1	
90501–26087	90501–27035	Spring, Shift & Select Lever Shaft	
33530–20780	33530–20790	Lever Assy, Shift	MX59
33820–2B540	33820–2B670	Cable Transmission Control Select	

ZOOM SIZED FOR PRINT

Parts Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

ZOOM SIZED FOR PRINT

Warranty Information